

 Acete tipuri de manometre industriale sunt destinate a func?iona ?i medii cu solicit?ri u?oare ?i medii.
Caracteristici tehnice:
-domenii de masur?:</p><p>0 1 bar 0 10 bar 0 100 bar
0 1,6 bar 0 16 bar 0 160 bar
0 2,5 bar 0 25 bar 0 250 bar
0 4 bar 0 40 bar 0 400 bar
0 6 bar 0 60 bar</p><p></p><p>-domenii de vacuum: -1 0bar; -1 +1bar; -1 +3bar; -1 +5bar; etc.
-diametru cadran: 40mm; 50mm; 63mm; 80mm; 100mm -clasa de precizie: 1,6 -carcasa: o?el negru (op?ional plastic) -geam: plexic ?lipsat
-element de masur?: tub Bourdon alam?
-montaj: radial sau axial -tip racord: G1/2; G1/4; G1/8 (op?ional alte dimensiuni sau standarde: metric, NPT) -accesorii: robine?i, garnituri, adaptori, sifoane
Certificat de test de la producator inclus Buletin verificare metrologica optional</p><h4> Fi?Catalog PDF</h4>